

FIELD INSPECTION REPORT

Date of Inspection : - 19.12.20		District : - Kishanganj	
Division : - Kishanganj-5		Length (km):- 26.80 K.M	
Name of the Road: PWD Jhalu Lodhabari Sohiya Balga Nizandra			
Scheme/Programme:		MAINTENANCE (N.M.P)	
Package No.: MR-N/19-Kishanganj-5/03		Road Id No.: NEA 220001296	
Status of the Project: ☒ Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	✓ S/U	
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. - N.A	Yes/No - H.A	
f)	Contraction Joints provided or not (CC Pavement) - N.A	Yes/No - H.A	
g)	Compaction of flank/slope & raincuts if any	Yes/No - work in progress	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - work in progress	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No - only informetry Board	
4.	Compliance History		
a)	Status of ATR's & any others	No ATR pending	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: . Er. Chandrashekhar Azad
(E.E)

19/12/20
(Signature)
(E.E)