

FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020 District: KAZMUR
Division : BHABUA Length (km): ~~1.8~~ 0.95
Name of the Road: BHABUA MOHANIA ROAD TO PIHRA VILLAGE
Scheme/Programme: MAINTENANCE
Package No.: Road Id No.: 10109640
Status of the Project: Ongoing Completed Under Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No } NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No }
g)	Compaction of flank slope & raincuts if any	Yes/No }
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI } NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI }
c)	Condition of railings/slab approach for Bridges	S/SRI }
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI) ✓

Unsatisfactory (U)

Riding quality of surface is good.

NAME: E. Arun Kumar Mahato

Armed
(Signature) 18-12-20