

FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020 District: Kaimur
 Division : Bhabua Length (km): 2.6 km.
 Name of the Road: Bagli Misra to Shwarpur via Kurari Torua Rampur Road
 Scheme/Programme: MAINTENANCE

Package No.: Road Id No.:
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity/Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI
c)	Condition of railings/slab approach for Bridges	S/SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Arjun Kumar Mahb
 18.12.2020
 (Signature)

NAME: Er. Arun Kumar Mahb.