

# FIELD INSPECTION REPORT

Date of Inspection :		18/12/2020	District :		Munglur
Division :		Kharagpur - Tapatpur	Length (Km) :		1.55 Km
Name of the Road :		Loly mukwa to Bangama			
Scheme/Programme :		MAINTENANCE ✓			
Package No. :		BR-22R-108	Road Id No. :		N/A
Status of the Project :		Ongoing/Completed/Under Maintenance ✓			
Work is a case of :		New Connectivity/Up gradation/Maintenance			
Sl. No.	Parameters to be checked			Remarks	
1	Pavement				
a)	Road Junction condition			S/U	S
b)	Condition of Surfacing			S/U	S
c)	Riding Quality			S/U	S
d)	Road Camber			S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any			Yes/No	Yes
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	N/A
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	N/A
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained			Yes/No	NO
4	Compliance History				
a)	Status of ATR's & any others			NO	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Shailendra K.  
DESIGNATION: J.E.

*[Signature]*  
(Signature)