

FIELD INSPECTION REPORT

Date of Inspection:	18/12/2020	District:	Sheikhpura
Division:	Sheikhpura	Length (km):	1.068 KM
Name of the Road:	L047-0702 To Dharampur		
Scheme/Programme:	MAINTENANCE	PMU 34 (under S. & M. Maint.)	
Package No.:	BR-31R-070	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	
c)	Condition of railings/slab/approach for Bridges	S/SR/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board 5m & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance H.O. 103		
a)	Status of ATR's & any others	—	

Raincuts found at some places.

Head walls H.P.C broken at some places.

N/A

N/A

200m stones not maintained properly.

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Signature
18/12/20

NAME: SANGRAM HEMBRAM

DESIGNATION: A.E.