

# FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020		District: SUPAUL
Division : SUPAUL		Length (km): 2.2041
Name of the Road: TEL to Solanpur (GR 35R-075)		
Scheme/Programme: MAINTENANCE		
Package No.: GR 35R-075		Road Id No.: 21004902061
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
<b>1. Pavement</b>		
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U (Some portion damaged & needs repair)
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
<b>2. Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/S/R/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/S/R/U
c)	Condition of railings/slab/approach for Bridges	S/S/R/U ✓
<b>3. Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
<b>4. Compliance History</b>		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓ SRI
Unsatisfactory (U)	

NAME: SUNIL KUMAR BHARTI

DESIGNATION: JUNIOR ENGINEER

*Sunil Kumar Bharti*  
(Signature)