

FIELD INSPECTION REPORT

Date of Inspection : 17/12/2020	District: Purnea	
Division : R.W.D. Div - Purnea	Length (km): 2.102 Km	
Name of the Road: Aojamun Devstara Chaur to Mahi Sthana		
Scheme/Programme:	MAINTENANCE	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing ☒ Completed ☐ Under Maintenance ☐	
Work is a case of:	New Connectivity ☒ Up gradation ☐ Maintenance ☐	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	LSU
b)	Condition of Surfacing	LSU
c)	Riding Quality	LSU
d)	Road Camber	LSU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	LS/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	LS/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Mumukshu Das
(Signature) 17/12/2020
JC

NAME:

DESIGNATION: