

FIELD INSPECTION REPORT

Date of Inspection : 19/11/2020	District: Purnea
Division : Dhanbad	Length (km): 3.30 km
Name of the Road: Michela To Sarnaha Paswan Road via Chauriyo	
Scheme Programme: MAINTENANCE	
Package No.	Road Id No.:
Status of the Project: Ongoing/Completed Under Maintenance	
Work is a case of: New Connectivity Up gradation Maintenance	

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	- SU
b)	Condition of Surfacing	- SU
c)	Riding Quality	- SU
d)	Road Camber	- SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	- Yes/No
g)	Compaction of flank/slope & raincuts if any	- Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	- S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	- S/SRI/U
c)	Condition of railings/slab/approach for Bridges	- S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Sh 19/11/2020
(Signature)

NAME:

DESIGNATION: