

FIELD INSPECTION REPORT


Date of Inspection : 18/12/2020		District: Nalanda	
Division : Bihar & Darf		Length (km): 2.039	
Name of the Road: Benar - Sakeshda Road To Tagnipur			
Scheme/Programme:		MAINTENANCE MMGSY - SC	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	- No -

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

* Partially Road crust damage in Flood Restoration estimate submitted.


 18/12/2020
 (Signature)

NAME: ~~LEE~~ Mukesh Yadav

DESIGNATION: J.E.