

FIELD INSPECTION REPORT

Date of Inspection :		District: Muzaffargarh	
Division : Muzaffargarh East-01		Length (km): 0.900 km	
Name of the Road: Dardha Siho Path Sitaray Thakur house to Dardha Siho		Road Id No.: 315072/3016	
Scheme/Programme: MAINTENANCE		Path Gansar mahato house	
Package No.:		Road Id No.: 315072/3016	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U ✓	
c)	Riding Quality	S/U	
d)	Road Camber	Yes/No ✓	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage	✓S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U	
3.	Road Furniture	Yes/No ✓	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

[Signature]
19.12.2020
SE

(Signature)

NAME:

DESIGNATION: