

FIELD INSPECTION REPORT

Date of Inspection: 19.12.2020		District:- Sitamarhi.
Division:-RWD, Works Div. Pupri.		Length (km):- 1.7
Name of the Road:- ⁶²³ Choranth to musliya		
Scheme/Programme:-		MAINTENANCE
Package No.:- BR33R-383		Road Id No.: 31607802017
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/✓SRI/U
b)	Condition of Abutments & Wing walls, Slab in RCC culverts	S/✓SRI/U
c)	Condition of railing/slab/approach for bridges	S/✓SRI/U
3.	Road Furniture	
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained	Yes/✓No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : SRI

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:- SHIVENDRA KR. RAJAK

Shm
18/12/20
(Signature)

DESIGNATION:-