


## FIELD INSPECTION REPORT

Date of Inspection: 18.12.2020		District:- Sitamarhi.
Division:-RWD, Works Div. Pupri.		Length (km):-
Name of the Road:- LOT 2 BAJET pur PMGSY Road House of Saloo Raut to Jankha-Jabna.		
Scheme/Programme:-		MAINTENANCE
Package No.:- BR-33R-313		Road Id No.: 31607802072
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		<input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance <input checked="" type="checkbox"/>
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<input checked="" type="checkbox"/> S/U
b)	Condition of Surfacing	S/U <input checked="" type="checkbox"/>
c)	Riding Quality	S/U <input checked="" type="checkbox"/>
d)	Road Camber	<input checked="" type="checkbox"/> S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	<input checked="" type="checkbox"/> Yes/No
f)	Contraction Joints provided or not (CC Pavement)	<input checked="" type="checkbox"/> Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No <input checked="" type="checkbox"/>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <input checked="" type="checkbox"/>
b)	Condition of Abutments & Wing walls, Slab in RCC culverts	S/SRI/U <input checked="" type="checkbox"/>
c)	Condition of railing/slab/approach for bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained	Yes/No <input checked="" type="checkbox"/>
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	" U "

Name:- Ramesh Kumar Satyarthi

  
 18.12.2020  
 (Signature)

DESIGNATION:- A.E