

FIELD INSPECTION REPORT

Date of Inspection : 17-12-2020	District: NALANDA	
Division : HARNAUT	Length (km): 0.850 km	
Name of the Road: Govind Govind Pur to Dayalpur via Mamurabad		
Scheme/Programme: MAINTENANCE	Construction	
Package No.:	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance	✓	
Work is a case of: ✓ New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Dr. V. V. Verma
17-12-2020
(Signature)

NAME: AJAY KUMAR VERMA

DESIGNATION: JUNIOR Engineer