FIELD INSPECTION REPORT

| Date of Inspection: | 21112120 | District: East chambaran | |
|--|--|--|--|
| Division: Moti Rade | | Length (km): 1. 48 km. | |
| Name of the Road: A | mrein Thateur. | to halbub chaudfary Kustlar | |
| Scheme/Programme: | MAINTENANCE | GTSNY | |
| Package No.: | | Road Id No.: - | |
| Status of the Project: | Ongoing/Completed/Under Maintenance | | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance | | |
| The second secon | with a later than the same | 1 O Tanasa Tanas | |

| Sl. No. | Parameters to be checked | Remarks | |
|---------|--|---------|--|
| 1. | Pavement | | |
| a) | Road Junction condition | \8/U | |
| b) | Condition of Surfacing | ·S/U | |
| c) | Riding Quality | -8/U | |
| d) | Road Camber | √S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | Yes/No | |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | 8/SRI/U | |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No | |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | -NIA | |

Overall Rating :

| Satisfactory (S) | , 2, |
|---|------|
| Satisfactory but requires Improvement (SRI) | - / |
| Unsatisfactory (U) | = |

(Signature)

NAME: makeshwar sharmes

DESIGNATION: J.E.