FIELD INSPECTION REPORT

Date of	Inspection : 401 al	- ILLE HASPECTIO	JN REPORT	
Date of Inspection: 12/12/2020			District : East Champaran	
Division : Chakia				
Name of	the Road : NH-28 C	hintamapur Salv	Andre Coult he at	
Name of the Road: NH-28 Chintamopur Salyandra Raul ka ghar se Scheme/Programme: MAINTENANCE			Chin homan Air	
Package No.: Road ID No.:				
Status of the Project :		Ongoing/Completed/Under Maintenance		
14/- 1 -				
SI. No.	Parameters to be checked			
1,	Pavement			Remarks
a)	Road Junction condition			
b)	Condition of Surfacing			- 5 -
c)	Riding Quality			- S -
d)	Road Camber			-5-
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			-SRI-
f)	Contraction Joints provided or not (CC Pavement)			- 5-
g)	Compaction of flank/slope & raincuts if any			- S -
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			-SRI-
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			-S-
c)	Condition of railings/slab/approach for Bridges			- 5RI-
3,	Road Furniture			76.
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			~ SRI-
4,	Compliance History			241
a)	Status of ATR's & any others			N/A'
				, , ,
	Overall Rating : Satisfactory (S)			1 14
	18	Satisfactory but requires	improvement (SRI)	-SRF
	<u></u>	Insatisfactory (U)		

NAME:

(Signature)

DESIGNATION: