

FIELD INSPECTION REPORT

Date of Inspection: 15-12-2020 District: West Champaran
 Division: RWD, Narkatiyagan Length (km): 1.180
 Name of the Road: TOS to Langri (VR34)
 Scheme/Programme: MAINTENANCE
 Package No.: BR-37R-400 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	U
b)	Condition of Surfacing	U
c)	Riding Quality	U
d)	Road Camber	U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement,	Yes
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	-
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U

Shah
 15-12-20
 (Signature)

NAME: Md. Shahid Ashraf

DESIGNATION: A-E