

FIELD INSPECTION REPORT

Date of Inspection :	17.12.2020	District:	W. Champaran
Division :	Narbhatiagang	Length (km):	1.647 Km
Name of the Road:	403 to Bhatuhwa		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-37P-406	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <i>pmrny</i>		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	SPT	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—	
f)	Contraction Joints provided or not (CC Pavement)	—	
g)	Compaction of flank/slope & raincuts if any	—	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	—	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—	
c)	Condition of railings/slab/approach for Bridges	—	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	SPT	
4.	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME: Chandradeo Pd

DESIGNATION: JE

Chandradeo Pd
17/12/20
(Signature)
JE