

FIELD INSPECTION REPORT


Date of Inspection : 18.12.20	District: Nalanda
Division : HILSA	Length (km): 1.2 km
Name of the Road: Kora Salem road to Golempur MMGSY	
Scheme/Programme: MAINTENANCE	Maintenance
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Under Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	U S
b)	Condition of Surfacing	U S
c)	Riding Quality	U S
d)	Road Camber	U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Y No Yes
f)	Contraction Joints provided or not (CC Pavement)	Y No Yes
g)	Compaction of flank/slope & raincuts if any	Y No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/RI/U RI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/RI/U RI
c)	Condition of railings/slab/approach for Bridges	S/RI/U RI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Y No No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

Pradeep Kumar Singh
SK

 (Signature)
 18/12/20
 SK