## FIELD INSPECTION REPORT

Date of	Inspection: 1242 2000 District: Sanga	Ch402
Division	1: Pach April Sway Scorer Length (km): 24	
Name of	the Road: Tou Gathua to sah tola	
	Programme:   MAINTENANCE	AND DESCRIPTION OF
Package		
	of the Project: Ongoing/Completed/Under Maintenance a case of: New Connectivity/Un gradation/ Mainten	
	and all francisco constitution	ance
SLAG	Parameters to be checked	Remarks
1.	Pavement	
2)	Road Junction condition St	
b)	Condition of Surfacing	SU
0)	Riding Quality	-su
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks aggregates in case of CC Pavement.	s, exposed Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	YesNo
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including	its painting S/SRJ/U
5)	Condition of Abutment & Wing walls, Slab in RCC culve	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/kn stones/Pavement road markings are provided and maintain	n & 200m Yes/No
4	Compliance History	ARTER STREET
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	SERVE A
Satisfactory but requires Improvement (SRI)	SPE
Unsatisfactory (U)	

NAME: And precedo Designation:

(Signature)