6

## FIELD INSPECTION REPORT

Date of Inspection: 16.12.2020		District: Samastipur			
Division: RWD Dalsinghsarai			Length(km): 2.202	9 Ki	
Nan	me of Road: Tos-	yogichoese To ku	Shwaha Joles.		
Sch	eme / Programme:	MAINTENANCE			
Package No: Mmbsy			Road Id No:		
		igoing/Completed/Under M			
	rk is a case of:	New Connectivity/ Up gra	dation/ Maintenance /		
SI. No	Parameters to be Checked Rema			Rem: . ks	
1	Pavement				
a)	Road Junction Condition			9	
b)	Condition of Surfacing '			5	
e)	Riding Quality			5	
d)	Road Camber			S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			5	
t)	Construction Joint provided or not(CC Pavement)			S	
9)	Compaction of flank/slope & raincuts if any				
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting -			S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			5	
c)	Condition of railings/slab/approach for Bridge			MIA	
3	Road Furniture				
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			5	
4	Compliance History				
a)	Status of ATR's &	Status of ATR's & any others			

Overall Rating :

Satisfactory(S)	8	
Satisfactory but requires Improvement(SRI)		
Unsatisfactory(U)		

(Sign: 110)

NAME: And Presson DESIGNATION: 525