


FIELD INSPECTION REPORT

Date of Inspection: 15.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 2.110 km
Name of Road: NH 28 near Satapur to Andaha.		
Scheme / Programme:		MAINTENANCE
Package No:	mmbsy	Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	N.A
f)	Constraction Joint provided or not(CC Pavement)	N.A
g)	Compaction of flank/slope & raincuts if any	SPT
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SPT
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SPT
Unsatisfactory(U)	


 15-12-2020
 (Signature)

NAME: Anil Prasad
 DESIGNATION: DV