

FIELD INSPECTION REPORT

Date of Inspection: 16.12.2020		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 1.25/km	
Name of Road: 2026 Rewari High School to Suryajara			
Scheme / Programme:		MAINTENANCE	
Package No: mm684		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked	Remarks	ks
1	Pavement		
a)	Road Junction Condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S	
f)	Constraction Joint provided or not(CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridge		
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S	
4	Compliance History		
a)	Status of ATR's & any others	N	

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

NAME:

DESIGNATION :

Anil Prasad

SO

[Signature]
16.12.2020
(Sign. etc)