

FIELD INSPECTION REPORT

Date of Inspection :		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 5.48 km.	
Name of the Road : Samheula Jagdishpur and Road Ladon River Pul more to Ganges, Kankhaya, Middle School more.			
Scheme / Programme :		NABARD.	
Package No :		Road Id No : 20703203007.	
Status of the Project :		Ongoing / Completed / Under Maintenance	
Work is a case of :		New Connectivity / Up gradation / Maintenance	
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Cmpaction of flank/slope & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / KM & 200m stones / Pavement road markings are provided and maintained.	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	
Overall Rating			
	Satisfactory (S)	/	
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)	/	

Note :

BT. Causal damaged in some part and. Logo brand Not print & maintained.

NAME : Rajkishor Rajah
DESIGNATION : A.E

Signature
17.12.20