

FIELD INSPECTION REPORT

Date of Inspection: 17.12.2020 District: panna
 Division: Borth Length (km): 3.71 km
 Name of the Road: To 2nd stage pvt. Bachel.
 Scheme/Programme: MAINTENANCE Road Id No.:
 Package No.:
 Status of the Project: Ongoing Completion/Under Maintenance
 Work is a case of: New Construction/Upgradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	✓
a)	Road Junction condition	SU ✓
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	Variable ✓
e)	Whether free from defects such as debris rocks, exposed aggregates in case of CC Pavement.	Variable ✓
f)	Construction joints provided or not (CC Pavement)	Variable ✓
g)	Compaction of bank slopes & shoulders if any	Variable ✓
2.	Cross Drainage	S/SRI
a)	Condition of head walls in Stone pipe culverts including its painting	S/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI
c)	Condition of railings/slab approach for Bridges	S/SRI
3.	Road Furniture	Variable ✓
a)	Whether sign boards/informatory cautionary Board/Sign & Road stones/Pavement road markings are provided and maintained	Variable ✓
4.	Compliance History	
a)	Status of ATR, CR & any other	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

"SRI"

Bishu Prasad Singh
 Junior Engineer
 AME

17/12/2020
 (Signature)