FIELD INSPECTION REPORT

Date of Inspection:	18-12-20-20	District: Nalanda
Division: Bikary	Mosil	Length (km): 0.953 RM.
Name of the Road: L	-027 Tilori To	GLASPUT (VR 52)
Scheme/Programme:	MAINTENANCE	Pmssy.
Package No.: BR-	24 R-301	Road Id No.:
Status of the Project	: Ongoing/Complete	d/Under Maintenance
Work is a case of:	New Connectivity/	Up gradation/ Maintenance
SI. No.	_	o he checked

I. No.	Parameters to be checked	Remarks
1.	Pavement	
n)	Road Junction condition	S/U
b)	Condition of Surfacing	
c)	Riding Quality	S/U
d)	Road Camber	S/U
c)	Whether free from defects such as visible cracks, exposed	S/U
	tes said in case of the Pavement.	Yes/No
t)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	1 03/10
a)	Condition of head walls in Hume pipe culverts including its painting	0/00
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slah/approach for Bridges	S/SRI/U
; . 3. ·	Road Furniture	S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200n stones/Pavement road markings are provided and maintained	1 Yes/No
有识	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)	C
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: ADVING Kelhay
DESIGNATION: JULIUS Fongines