

FIELD INSPECTION REPORT

Date of Inspection : 21-12-2020 District: Buxar
 Division : Buxar Length (km): 0.185 Km
 Name of the Road: Dhanosi-Tijera path to Mahadali tola hote highway thana
 Scheme/Programme: MAINTENANCE MMSJ (SC) main road tak.
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance ongoing.
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	NA S/U
d)	Road Camber	R ✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	NA Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	X

Mubarak Hussain Ansari

NAME:

Mubarak
 21-12-2020
 (Signature)
 Rajpur Block.