FIELD INSPECTION REPORT

ate of In	spection:	18:12:2020	District: Banks		
Division: Borneg-1 Length (km): 1.10					
Name of the Road: Kashig to Rajbyr, Mauribyr Road					
Scheme/Programme: MAINTENANCE					
ackage l	and the second second		Road Id No.:		
			ted/Under Maintenance		
Nork is a	a case of:	New Connectivity	y/Up gradation/ Maintenance	50 St. 100	
31. No.		Parameters	(olbe chacked a frequency of the second	Remireks	
1.	Pavement				
a)	Road Junction	\\$/Û			
b)	Condition of	1.8/U			
c)	Riding Quali	√8/U.			
d).	Road Cambe	<i>\81</i> U			
c)	Whether fre	Yes/No			
f)	Contraction.	Yes/No			
g)	Compaction	Yes/Nø/			
2.	Cross Drain	iliko.		de de	
· a)	Condition of	S/SPA/U			
b)	Condition of	S/SRI/U			
c)	Condition o	.S/SRI/U			
3.	Road Furn				
a)	Whether si stones/Pave	Yes/No			
4.3	Complianc	eHistory & FE			
a)	Status of A	TR's & any others			

Overall Rating

Satisfactory (S)	A SAN				
Satisfactory but rec	uires Imp	rovement	(SRI)	SF	? I
Unsatisfactory (U)	Care Francy	A MEDITE LATER	1.00	The state of the s	

Okumal 18-12-2020 (Signature)

NAME: DHARMVEER KUMAR

DESIGNATION: J.E.