

FIELD INSPECTION REPORT

Date of Inspection: 18/12/2020		District: Kishanganj
Division: Kishanganj-1		Length(km): 0.350 km
Name of the Road: Bheg Baisa Uttar Tola Masjid to Co		
Scheme/Programme: ATINY, Name of Agency - Mukesh Kr Singh		
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed /Under Maintenance ✓
Work is a case of:		New Connectivity/ Up gradation / Maintenance ✓

Sl. No	Parameters to be checked	Remarks
1.	Pavement	✓ S/U
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as <u>visible cracks</u> , <u>exposed aggregates</u> in case of CC Pavement. <u>Yes exposed aggregates</u> ^{No}	✓ Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank / shop & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained ^{200m, km Stone not found}	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	1

Overall Rating :

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	-


 18/12/20
 (Signature)

NAME: Ranjeet Kumar