


FIELD INSPECTION REPORT

Date of Inspection: 18/12/2020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 0.350 km	
Name of the Road: Dahuabadi to MMGSY Road			
Scheme/Programme: ATSNY			
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance <input checked="" type="checkbox"/>	
Work is a case of:		New Connectivity/ Up gradation / Maintenance <input checked="" type="checkbox"/>	
S1. No	<u>Parameters to be checked</u>		Remarks
1.	Pavement		<input checked="" type="checkbox"/> S/U
a)	Road Junction Condition		<input checked="" type="checkbox"/> S/U
b)	Condition of Surfacing		<input checked="" type="checkbox"/> S/U
c)	Riding Quality		<input checked="" type="checkbox"/> S/U
d)	Road Camber		<input checked="" type="checkbox"/> S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No <input checked="" type="checkbox"/>
f)	Contraction Joints Provided or not (CC Pavement)		<input checked="" type="checkbox"/> Yes/No
g)	Compaction of flank / shop & raincuts if any raincuts found.		<input checked="" type="checkbox"/> Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m 200m, stones/Pavement road markings are provided and maintained km stone not found.		Yes/No <input checked="" type="checkbox"/>
4.	Compliance History		
a)	Status of ATR's & any others		-

Overall Rating :

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	-


 (Signature)

NAME: Ranjeet Kumar