FIELD INSPECTION REPORT

	y and a specific author for the second secon			
Date of	Inspection: 18	12/2020 District: Kishanganj		
Division	n: Kishan	ganj -1 Length(km): 0,400 km		
	of the Road:	GISTY Laiter to Feerangur.		
Scheme	e/Programme:	GTSNY		
Packag		Road Id No.:		
Status of the Project:		Ongoing/Completed /Under Maintenance		
	s a case of:	New Connectivity/ Up gradation / Maintenance		
S1. No		Parameters to be checked,	Remarks	
1.	Pavement		VS/U	
a)	Road Junction	Condition	VS/U	
b)	Condition of Su	ırfacing	VS/U	
c)	Riding Quality		VS/U	
d)	Road Camber		VS/U	
e)	Whether free fin case of CC P	from defects such as visible cracks, exposed aggregates avement.	Yes/No	
f)	Contraction Joints Provided or not (CC Pavement)		₩es/No	
g)	Compaction of	f flank / shop & raincuts if any	Yes/No	
2.	Cross Drainage			
a)	Condition of h	ead walls in Hume pipe culverts including its Painting	S/SRI/U	
b)	Condition of A	Abutment & Wing walls, slab in RCG culverts	S/SRI/U	
c)	Condition of r	ailings/Slab/approach for Bridges	S/SRI/U	
3.	Road Furnitur			
a)	Whether sign stones/Paven	boards/informatory/cautionary Board/km & 200m nent road markings are provided and maintained	✓ Yes/No	
4.	Compliance History			
a)	Status of ATR	's & any others		

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	• -

(Signature) 20

NAME: Ranjeet kumur