FIELD INSPECTION REPORT

Date of Inspection: 17-12-20		District:- Sitamarhi	District:- Sitamarhi.		
Division:-RWD, Works Div. Pupri.			Length (km):- 6.	Length (km):- 6.779	
Name o	f the Road:- 🗬	DE LIDI Lakha	mipur to sagdishpy.	•	
Scheme	/Programme:-	MAINTEN	IANCE		
Package	e No .:- BR 33	R601	Road Id No.: La 314	607802105	
Status o	of the Project:	Ongoing/Compl	leted/Under Maintenanc	e	
Work is	a case of:	New Connectivi	ty/Up gradation/ Mainte	enance 🕌	
Sl. No.		Parameters to be	checked	Remarks	
1.	Pavement				
a) .	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			~\$7U	
d)	Road Camber			~S/U	
e)	The state of the s	from defects s gates in case of (uch as visible cracks, CC Pavement	Yes/No~	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No *	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainag	ge			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U		
b)	Condition of Abutments & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railing/slab/approach for bridges			S/SRI/U	
3.	Road Furnitu	re			
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained			Yes/No~	
4.	Compliance History				
a)		's & any others		No	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Name: - Praveen Kumar Panoley

(Signature)

DESIGNATION:- ७€