


FIELD INSPECTION REPORT

Date of Inspection :	17.12.2020	District:	Ar. Champaran
Division :	Marketing	Length (km):	1.300 km
Name of the Road:	T02 Sishaula to Pachoukhya		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-372-603	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance Primary		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S	
f)	Contraction Joints provided or not (CC Pavement)	-	
g)	Compaction of flank/slope & raincuts if any	-	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	-	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-	
c)	Condition of railings/slab/approach for Bridges	-	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S	
4.	Compliance History		
a)	Status of ATR's & any others	-	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-


17/12/20
(Signature)

NAME: Chandradeo Patel
DESIGNATION: JE