

FIELD INSPECTION REPORT

| | |
|--|--|
| Date of Inspection : 20.12.2020 | District: W. Champaran |
| Division : Bagaha - I | Length (km): 0.50 km |
| Name of the Road: Tishut Main Canal to Kuriya tola | |
| Scheme/Programme: | MAINTENANCE |
| Package No.: | Road Id No.: |
| Status of the Project: | Ongoing/Completed/Under Maintenance ✓ |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance ✓ |


| Sl. No. | Parameters to be checked | Remarks |
|---------|--|----------|
| 1. | Pavement | |
| a) | Road Junction condition | ✓S/U |
| b) | Condition of Surfacing | ✓S/U |
| c) | Riding Quality | ✓S/U |
| d) | Road Camber | ✓S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | ✓Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | ✓Yes/No |
| g) | Compaction of flank/slope & raincuts if any | ✓Yes/No |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | ✓S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | ✓S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | ✓S/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | No |

Overall Rating :

| | |
|---|-----|
| Satisfactory (S) | (S) |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME: Deepak Kumar

DESIGNATION: JE

(Signature) 
19/12/20