

FIELD INSPECTION REPORT

Date of Inspection :	15/12/2020	District:	East Champaran
Division :	Motihari	Length (km):	1.305
Name of the Road:	REO Dhekhan Bandaha to Chairpur		
Scheme/Programme:	MAINTENANCE	NABARD	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/N
b)	Condition of Surfacing	S/N
c)	Riding Quality	S/N
d)	Road Camber	S/N
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained <i>Repairing Board, Kon Stone / 200m stones</i>	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others <i>(Already submitted)</i>	Pending

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Amim
16/12/2020
(Signature)

NAME: *Arul Kumar Pd. Thakur*

DESIGNATION: *T.E*