## FIELD INSPECTION REPORT

te of In	spection: 18	112/2020	District: Nalander		
Division: Bihar Edwil			Length (km): 0.500 K·W·		
lame of t	he Rond: Cov	reforction of Roa	d From Benaz Sak solu	ey Road To	Mahn
cheme/P	rogramme:	MAINTENANCE	NABARD		
Package No.:			Road Id No.:		
	the Project:	Ongoing/Completed/			_
Work is a	case of:	New Connectivity/U	p gradation/ Maintenance		
Sl. No.	l. No. Parameters to be checked			Remark	KS.
1.	Pavement				
a)	Road Junction condition			S/U	S
b)	Condition of Surfacing			S/U	- S
c)	Riding Quality			S/U	-
d)	Road Camber			S/U	_ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	- y
f)_	Contraction Joints provided or not (CC Pavement)			Yes/No	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				<b>ا</b> لاو
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	ND
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	Nn
3.	Road Furniture				NA
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	yes
4. 6	Compliance History				
a)	Status of ATR's & any others			- No -	-

Satisfactory (S)	6	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

(Signature)

NAME: Mukesh Zadau

DESIGNATION: J.C.