


# FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 0.5614 km	
Name of the Road : Udhadih PMGSY road to Anandi Roy's house			
Scheme / Programme : 1. MMGSY (SC)			
Package No. :		Road Id No. : 20703201335	
Status of the Project : Ongoing / Completed / Under Maintenance			
Work is a case of : New Connectivity / Up gradation / Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U ✓	
b)	Condition of Surfacing	S/U ✓	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes / No	
g)	Compaction of flank/slope & raincuts if any	✓Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	] NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	No	
Overall Rating			
	Satisfactory (S)	1	
	Satisfactory but requires Improvement (SRI)	1	
	Unsatisfactory (U)	U	

Note : BT damage in some part Flank and 2 Logo board not properly maintain

NAME : Rutkishwar Rajan  
DESIGNATION : A.E

  
18.12.2020  
Signature