


## FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) :	
Name of the Road : Deodha Gram Vishakhasthan to Motichak			
Scheme / Programme :			
Package No. : MMGSY (SC)		Road Id No. : 20703201337	
Status of the Project : Ongoing / Completed / Under Maintenance <input checked="" type="checkbox"/>			
Work is a case of : New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U <input checked="" type="checkbox"/>	
b)	Condition of Surfacing	S/U <input checked="" type="checkbox"/>	
c)	Riding Quality	S/U <input checked="" type="checkbox"/>	
d)	Road Camber	<input checked="" type="checkbox"/> S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <input checked="" type="checkbox"/>	
f)	Contraction Joints provided or not (CC Pavement)	<input checked="" type="checkbox"/> Yes/No	
g)	Compaction of flank/slope & raincuts if any	<input checked="" type="checkbox"/> Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	<input type="checkbox"/>
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	<input type="checkbox"/> NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	<input type="checkbox"/>
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes/No <input checked="" type="checkbox"/>	
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating			
	Satisfactory (S)	1	
	Satisfactory but requires Improvement (SRI)	1	
	Unsatisfactory (U)	'U'	

Note: BT damage in some part of road Riding quality is not good Logo board not properly maintain

NAME: Rajkishor Rajah

DESIGNATION: A E

  
18.12.2020  
Signature A E