

FIELD INSPECTION REPORT

Date of Inspection :		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 3.186 KM	
Name of the Road : Katahara (PMWSY) Road Jahn paswan's house to Udhadih			
Scheme / Programme :			
Package No : NabuA		Road Id No : 20703200312	
Status of the Project : Ongoing / Completed / Under Maintenance ✓			
Work is a case of : New Connectivity / Up gradation / Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U ✓	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No ✓	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes / No	
g)	Cmpaction of flank/slope & raincuts if any	Yes / No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	] NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No ✓	
4.	Compliance History		
a)	Status of ATR's & any others		
Overall Rating		No	
	Satisfactory (S)	1	
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (II)	1	

Note :

Logo board not properly maintain in post 2
200m stone not found

NAME : Rajkishor Rajah

DESIGNATION : A.E

Signature 
18.12.2020
A.E