FIELD INSPECTION REPORT

Date of Inspection :	16/12/2020	District: James	
Division: James		Length (km): 0.307 Km	
		kanwa Pacherwari PMYSY.	
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.: 2080 41018 21	
Status of the Project:		ed/Under Maintenance	
Work is a case of:	New Connectivity	/Up gradation/ Maintenance	
Sl. No.	Parameters i	o be checked Remarks	
1 Pavement		TO THE TAXABLE PROPERTY OF THE	

SI. No.	Parameter to be diesked	Remarks
1.	Pavement	
a)	Road Junction condition	SAU
b)	Condition of Surfacing	SAU
c)	Riding Quality	SAU
d)	Road Camber	SAU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	1 12531 163 1 1645 - 2 164
a)	Condition of head walls in Hume pipe culverts including its painting	- 8 /8RI/ U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/ SRI/ U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Forniture	Page 1
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
**************************************	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

AE, Lexingus

(Signature)

NAME:

DESIGNATION: