

FIELD INSPECTION REPORT

MMSY

Date of Inspection : 21.12.20		District: Buxar	
Division : Buxar		Length (km): 1.297 Km	
Name of the Road: Nager Nahar Sadak Rd to Hemija tali		Scheme/Programme: MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		Work is a case of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

NAME:

N.K. Hineshu
सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, राजपुर

(Signature)

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, राजपुर

21.12.20