Block - Piprahi

FIELD INSPECTION REPORT

Date of I	nspection: - 18-12-2020 District: - Sheohar	
	Length (km): -1.20 kM	
Name of	the Road: -Dekuli Dharampur Kiti U. Kal to Kam swarain Ko	y Kelahar Ta
Schemen	1717	
Package	177	
	the Project: Ongoing/Completed/Under Maintenance	
Work is a	A case of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	V S/U
b)	Condition of Surfacing	√s/u
c)	Riding Quality	S/U
d)	Road Camber	√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	√Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	·
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	.T. R. is pen
a) Status of ATR's & any others No Atr R. is per in this scheme.		
Satisfactory (S)		"5"
	Satisfactory but requires Improvement (SRI)	
,	Unsatisfactory (U)	

(Signature)

NAME: - Sudhir Kumar

DESIGNATION: - A.E.