

FIELD INSPECTION REPORT

Date of Inspection: 18.12.2020		District: Bhagalpur	
Division: Bhagalpur		Length (Km): 0.5004 km	
Name of the Road: Abhigant kumari road at 2nd km vijay sharma's house to upswasthya kendra & other rural link road			
Scheme / Programme: I			
Package No.: MMGSY (SC)		Road Id No.: 20703201348	
Status of the Project: Ongoing / Completed / Under Maintenance			
Work is a case of: New Connectivity / Up gradation / Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No ✓	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes / No	
g)	Compaction of flank/slope & raincuts if any	Yes / No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	] NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	✓ Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating:			
	Satisfactory (S)	S	
	Satisfactory but requires Improvement (SRI)		
	Unsatisfactory (U)		

Note :

NAME: Rajkishor Rajah
DESIGNATION: A.E

Signature: [Signature]
18.12.2020
A.E