

FIELD INSPECTION REPORT

Date of Inspection : 19.12.2020		District: Muzaffarpur
Division : Muzaffarpur East-01		Length (km):
Name of the Road: Balahi Inter College Pith road to Baisi Madhya		
Scheme/Programme: MAINTENANCE		Vidyalaya
Package No.:	Road Id No.: 31507201352	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ /U
d)	Road Camber	✓ /U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

Shanad
19-12-2020
SE

Shanad
19-12-2020
AE.
(Signature)

NAME:

DESIGNATION: