

FIELD INSPECTION REPORT

Date of Inspection:	17/12/2020	District:	Purnea
Division:	R.W.D Div - Purnea	Length (km):	0.350 km
Name of the Road:	Balug Tola to Durgah Ashan		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	L/S/U	
b)	Condition of Surfacing	L/S/U	
c)	Riding Quality	L/S/U	
d)	Road Camber	L/S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	L/Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	L/Yes/No	
g)	Compaction of flank/slope & raincuts if any	L/Yes/No	
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting.	L/S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	L/Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Munish Dey
(Signature) J.E

NAME:

DESIGNATION: