FIELD INSPECTION REPORT

Date of Inspection : 19-12-2020		District: East-champaran	
Division: paksidyal		Length (km): 1-0	
Name of the Road: 610	ulab Khan pcc	to Gulab Khan Briti	
Scheme/Programme:	MAINTENANCE	UTSNY	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	2
a)	Road Junction condition	
b)	Condition of Surfacing	48/U
c)	Riding Quality	SHO
d)	Road Camber	STU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	¥es/No
g)	Compaction of flank/slope & raincuts if any	¥es/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	"S#SRI/U
c)	Condition of railings/slab/approach for Bridges	-S/SRI/U
3.7	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4,	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

19.12.2020

(Signature)

NAME: Dramendra Kuma

DESIGNATION: