

FIELD INSPECTION REPORT

Date of Inspection : 18/12/2020		District : East Champaran
Division : Chakia		Length (Km): 0.85 km
Name of the Road : House of Devan sah sikrahna Jethbardi to house of niramunda		
Scheme/Programme :		MAINTENANCE
Package No.:		Road ID No.:
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	
1.	Pavement	Remarks
a)	Road Junction condition	N/A
b)	Condition of Surfacing	N/A
c)	Riding Quality	N/A
d)	Road Camber	-BS-
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts Including its painting	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-S-
c)	Condition of railings/slab/approach for Bridges	-S-
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	-SRI-
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	-SRI-
Unsatisfactory (U)	

NAME :

DESIGNATION :

(Signature)

Abhi
18/12/2020
JE