


FIELD INSPECTION REPORT

Date of Inspection: 18/12/2020	District: Krishnangam
Division: Krishnangam-1	Length(km): 0.450 km
Name of the Road: Madarsa Tola to 6075	
Scheme/Programme: GITNY	Agency - Naresw Kr Narala
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed /Under Maintenance
Work is a case of:	New Connectivity/ Up gradation / Maintenance

Sl. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints Provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank / shop & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓ km Stone ✓ 200m Stone not ✓
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	RI
Unsatisfactory(U)	-


 (Signature) 18/12/20

NAME: Ranjeet Kumar