

# FIELD INSPECTION REPORT

Date of Inspection : 16-12-2020	District: Supaul
Division : R.W.D. - Mirpur Division	Length (km): 2.00
Name of the Road: Bihari Sah House to Sachinwarayan Yadav House	
Scheme/Programme: MAINTENANCE - GTSNY	
Package No.:	Road Id No.: 21005001845
Status of the Project: Ongoing/Completed/Under Maintenance -	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	N/L

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature) 16/12/2020

NAME: - Raj Kumar Yadav

DESIGNATION: D.E.

Shaktiyahi  
R.W.D Division - Mirpur