

FIELD INSPECTION REPORT

Date of Inspection : 16-12-2020		District: Supaul
Division: RWD Birpur Division		Length (km): 0.300
Name of the Road: NH-57.37 km to Kailash house		
Scheme/Programme: MAINTENANCE - GTSNY		
Package No.:		Road Id No.: 21005001850
Status of the Project: Ongoing/Completed/Under Maintenance - Completed		
Work is a case of: New Connectivity/Up gradation/ Maintenance - New Connectivity		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature) 16/12/2020

NAME: - Raj Kumar Yadav

DESIGNATION: J.E.
RWD-Division Birpur
(Bakhtiyari)