

FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020	District: BUXAR
Division : Dumraon	Length (km): 1.795 km
Name of the Road: Kesath Chaugai Road Gada Gop Ke Dera to Shivpur Uttar to Kesath Basudeva Patel	
Scheme/Programme: MAINTENANCE	MMGSY (B RICS)
Package No.: -	Road Id No.: -
Status of the Project: Ongoing/Completed/Under Maintenance	Completed
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U S
b)	Condition of Surfacing	✓S/U S
c)	Riding Quality	✓S/U S
d)	Road Camber	✓S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	- No -

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Phu
21.12.2020
J-E

V. Kash
21.12.2020
AE

(Signature)

NAME: